





Nr	Ant	Ändring	Datum	Inf	Godk
----	-----	---------	-------	-----	------



Option:
Reveal lining on
threshold



Option:
Reveal lining on all
frame parts

Det.nr	Ant	Benämning	Material	Dimension	Anmärkning			
	Ritad/Konstr	Ansvarig	Kontr	Stand	Godkänd	Skala	Ersätter	Ersatt av
	U.C	AR						
Beskrivning							Datum	
1B Outward opened. Double Door							220214	
UL.ULN							Ritning.nr	
							100-5-419	

Nr	Ant	Ändring	Datum	Inf	Godk
----	-----	---------	-------	-----	------




Horizontal and vertical section of glazing of door leaf Outside <- Glass -> Inside

834PG, 835PG, 871PG, 992PG, 869PG2+1




819PG, 831PG2, 836PG, 838PG,
302PG2+1, 836PG1+3, 839PG1+3,
836PG3, 839PG3


820PG, 843PG, 892PG

Vertical



Horizontal



Det.nr	Ant	Benämning			Material	Dimension	Anmärkning		
		Ritad/Konstr	Ansvarig	Kontr	Stand	Godkänd	Skala	Ersätter	Ersatt av
		U.C	AR						
							Beskrivning Section of glazing 2B		Datum 220214
							Ritning.nr 100-5-419		